

L Number	Hits	Search Text	DB	Time stamp
1	31	(US-5918048-\$ or US-5930515-\$ or US-6594723-\$ or US-6795912-\$ or US-6745324-\$ or US-5878256-\$ or US-5623604-\$ or US-6009500-\$ or US-6581157-\$ or US-5452454-\$ or US-6438688-\$ or US-5859911-\$ or US-6640334-\$ or US-6615404-\$ or US-6594757-\$ or US-5826015-\$ or US-6266809-\$ or US-6167567-\$ or US-6539473-\$ or US-5901225-\$ or US-6324692-\$ or US-5701492-\$ or US-6308265-\$ or US-6718373-\$ or US-5948101-\$ or US-5325532-\$).did. or (US-6275931-\$ or US-5930504-\$ or US-5210854-\$ or US-6031867-\$).did. or (US-20020049898-\$).did.	USPAT; DERWENT	2004/10/27 11:40
2	3	((US-5918048-\$ or US-5930515-\$ or US-6594723-\$ or US-6795912-\$ or US-6745324-\$ or US-5878256-\$ or US-5623604-\$ or US-6009500-\$ or US-6581157-\$ or US-5452454-\$ or US-6438688-\$ or US-5859911-\$ or US-6640334-\$ or US-6615404-\$ or US-6594757-\$ or US-5826015-\$ or US-6266809-\$ or US-6167567-\$ or US-6539473-\$ or US-5901225-\$ or US-6324692-\$ or US-5701492-\$ or US-6308265-\$ or US-6718373-\$ or US-5948101-\$ or US-5325532-\$).did. or (US-6275931-\$ or US-5930504-\$ or US-5210854-\$ or US-6031867-\$).did. or (US-20020049898-\$).did.) and (eras\$3 near2 firmware)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/27 11:41
3	15	(eras\$3 near2 firmware) and (plurality with (clients OR (computer adj systems) OR systems))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/27 11:43
4	437	717/171-173.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/27 11:43
5	94	717/171-173.ccls. and firmware	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/27 11:43
6	36	(717/171-173.ccls. and firmware) and server and clients	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/27 11:44

7	21	((717/171-173.ccls. and firmware) and server and clients) and distributed	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/27 11:46
8	45	717/171-173.ccls. and (upgrad\$3 OR updat\$3) near2 (firmware OR bios)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/27 11:46
9	42	(717/171-173.ccls. and (upgrad\$3 OR updat\$3) near2 (firmware OR bios)) and network	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/27 11:46
-	1209	update and install and firmware	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/02 16:33
-	288	(update and install and firmware) and (non-volatile adj memory)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 10:21
-	123	((update and install and firmware) and (non-volatile adj memory)) and upgrade	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 10:22
-	1	"firmware upgrade patch"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:11
-	26	modify same boot same image	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:31
-	162	modify same boot same memory	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:33
-	136	modify same boot same memory	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:34
-	184	update near2 bios	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:34
-	84	(update near2 bios) and network	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:55

-	416	update near2 firmware	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:55
-	159	(update near2 firmware) and network	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:55
-	61	((update near2 firmware) and network) and boot	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 16:46
-	62	"flash application"	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 16:52
-	2	("5452454").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 16:54
-	2	("5623604").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 16:55
-	2	("5870610").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 16:55
-	328	firmware near2 upgrade	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 16:57
-	142	(firmware near2 upgrade) and "non-volatile"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 16:57
-	89	((firmware near2 upgrade) and "non-volatile") and boot	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 17:00
-	59	((firmware near2 upgrade) and "non-volatile") and boot	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 17:00
-	488	firmware near1 update	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 10:10

	422	(firmware near1 update) and memory	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 10:10
	258	((firmware near1 update) and memory) and ((local fixed) and storage)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 10:11
	5	(((firmware near1 update) and memory) and ((local fixed) and storage)) and (boot near2 (image request))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 10:11
	3	("5452454" "5623604" "5870610").PN.	USPAT	2003/07/01 10:17
	3	6266809.URPN.	USPAT	2003/07/01 10:26
	3535	(firmware BIOS operating\$1system) same (install\$5 (upgrade upgrading))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:32
	3511	(firmware BIOS) same (install\$5 (upgrade upgrading))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:32
	376	(firmware BIOS) same (install\$5 and (upgrade upgrading))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:33
	173	(firmware BIOS) same (install\$5 and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:36
	20	(firmware BIOS) same ((install\$5 with application) and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:39
	0	(firmware BIOS) same ((install\$5 adj application) and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:39
	0	(firmware BIOS) same ((install adj application) and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:39
	1	(firmware BIOS) same ((install\$ adj application) and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:40
	205	((install\$ adj application) and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:40

	49	((install adj application) and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:41
	363	((install adj application) installer) and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:05
	37	"install application" and upgrade	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:07
	63	software with (installer "install application")	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:09
	393	firmware\$1 with (upgrade install patch)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:10
	789	firmware\$1 with (upgrade install\$5 patch\$2)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:10
	76460	(firmware\$1 with (upgrade install\$5 patch\$2)) or BIOS	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:10
	1446	(firmware\$1 BIOS) with (upgrade install\$5 patch\$2)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:11
	53	((firmware\$1 BIOS) with (upgrade install\$5 patch\$2)) and installer	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:38
	140	(717/178).CCLS.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:39
	95	(717/178).CCLS.	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:39
	17	((717/178).CCLS.) and installer	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:40
	12	(((717/178).CCLS.) and installer) and (update or upgrade)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:40

	37	(system adj loader) and (memory adj2 address\$2) and boot	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/02 15:11
	55	(system adj loader) and (memory adj2 address\$2) and (modify\$3)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/02 15:11
	3	((system adj loader) with (modify\$3)) and (memory adj2 address\$2)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/02 15:12
	1	store\$3 and "system loader interface" and (fixed adj storage)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/02 16:37
	2	store\$3 and "system loader" and (fixed adj storage)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/02 16:37
	216	store\$3 and "system loader" and storage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/02 16:38
	116	store\$3 and "system loader" and fixed	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/02 16:38
	100	store\$3 and "system loader" and fixed	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/02 16:38
	0	install\$3 with software with (firmware adj update\$1)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/07 15:48
	20	software with (firmware adj update\$1)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/07 16:13
	2	remove with (firmware adj update\$1)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/07 16:15
	0	"remove the firmware update"	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/07 16:15
	17	firmware with patch with software	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/07 16:42

	11	(software adj patch\$2) with firmware	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/07 16:44
	11	(software adj patch\$2) with (firmware BIOS)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/07 16:44
	14	(software adj patch\$2) same (firmware BIOS)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/07 16:44
	5	(install\$5 adj3 (application program)) same erase same (old prior)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/22 12:27
	11	(install\$5 adj3 (application program)) same (erase uninstall) same version	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/22 12:27
	33	(firmware and network and install\$5).ab.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 12:37
	2	((firmware and network and install\$5).ab.) and (configuration with file)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 12:35
	4	(firmware and upgrade).ab. and network and (config\$7 near2 file)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 12:38
	388	(firmware and upgrade) and network and (config\$7 near2 file)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 12:39
	5	((firmware and upgrade) and network and (config\$7 near2 file)) and (boot near2 request)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 12:39
	44	(firmware and (updat\$3 OR upgrad\$3)).ab. and ((configuration OR setup OR updat\$3 OR install\$5) near2 file)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 12:40
	1	2001-217656.NRAN.	DERWENT	2003/11/17 12:48

	14	(US-6167567-\$ or US-6324692-\$ or US-5901225-\$ or US-5210854-\$ or US-6275931-\$ or US-5623604-\$ or US-5878256-\$ or US-6266809-\$ or US-5826015-\$ or US-5859911-\$ or US-6438688-\$ or US-6009500-\$ or US-6148387-\$ or US-6581157-\$).did.	USPAT	2003/11/17 12:49
	12	((US-6167567-\$ or US-6324692-\$ or US-5901225-\$ or US-5210854-\$ or US-6275931-\$ or US-5623604-\$ or US-5878256-\$ or US-6266809-\$ or US-5826015-\$ or US-5859911-\$ or US-6438688-\$ or US-6009500-\$ or US-6148387-\$ or US-6581157-\$).did.) and (boot\$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 12:52
	0	((US-6167567-\$ or US-6324692-\$ or US-5901225-\$ or US-5210854-\$ or US-6275931-\$ or US-5623604-\$ or US-5878256-\$ or US-6266809-\$ or US-5826015-\$ or US-5859911-\$ or US-6438688-\$ or US-6009500-\$ or US-6148387-\$ or US-6581157-\$).did.) and (bootable with kernel)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 12:53
	0	(bootable with kernel) and ((upgrad\$3 OR updat\$3) with firmware)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 12:53
	0	(boot\$1able with kernel) and ((upgrad\$3 OR updat\$3) with firmware)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 12:53
	1	(boot\$1able with kernel) and ((upgrad\$3 OR updat\$3) with firmware)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 12:53
	0	((US-6167567-\$ or US-6324692-\$ or US-5901225-\$ or US-5210854-\$ or US-6275931-\$ or US-5623604-\$ or US-5878256-\$ or US-6266809-\$ or US-5826015-\$ or US-5859911-\$ or US-6438688-\$ or US-6009500-\$ or US-6148387-\$ or US-6581157-\$).did.) and (bootable with kernel)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 12:54
	12	(boot adj2 disk) and temporary and (operating adj system) and ((updat\$3 OR upgrad\$3) with firmware)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 12:57
	156	717/173.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 12:57

	42	717/173.ccls. and (boot)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 12:57
	13	(717/173.ccls. and (boot)) and firmware	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 13:26
	2	5666293.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 13:03
	2	5647986.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/11/17 13:26
	27	("5388267" "5452339" "5473775" "5522076" "5535355" "5568641" "5579522" "5592669" "5630093" "5647986" "5666293" "5701492" "5748940" "5812883" "5930358" "5940074" "5966301" "6029046" "6035423" "6055632" "6085299" "6135651" "6148441" "6185678" "6253281" "6308265" "6385721" "2001/0026472").PN.	USPAT	2003/11/17 14:29
	1549	717/168-178.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 11:47
	310	717/168-178.ccls. and (firmware OR (flash near2 (upgrade OR update)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/13 16:45
	115	(717/168-178.ccls. and (firmware OR (flash near2 (upgrade OR update)))) and (\$2boot\$4 with (kernel OR kernal OR OS OR (operat\$3) OR system OR application))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/13 16:48
	105	((717/168-178.ccls. and (firmware OR (flash near2 (upgrade OR update)))) and (\$2boot\$4 with (kernel OR kernal OR OS OR (operat\$3) OR system OR application))) and (\$4ROM OR non\$1volatile)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/13 17:16
	160	717/168-178.ccls. and network and (boot\$4 with (replacement OR upgrad\$3 OR install\$5 OR image OR replac\$3))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/13 17:15

	137	(717/168-178.ccls. and network and (boot\$4 with (replacement OR upgrad\$3 OR install\$5 OR image OR replac\$3))) and (\$4ROM OR non\$1volatile)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/13 17:42
	19	((717/168-178.ccls. and network and (boot\$4 with (replacement OR upgrad\$3 OR install\$5 OR image OR replac\$3))) and (\$4ROM OR non\$1volatile)) and (boot with request)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/13 17:17
	40	((717/168-178.ccls. and network and (boot\$4 with (replacement OR upgrad\$3 OR install\$5 OR image OR replac\$3))) and (\$4ROM OR non\$1volatile)) and firmware	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/13 17:42
	362	boot adj image	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/14 10:35
	279	(boot adj image) and network	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/14 10:35
	80	((boot adj image) and network) and firmware	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/14 10:35
	70	(((boot adj image) and network) and firmware) and \$4ROM	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/14 10:54
	2	(((boot adj image) and network) and firmware) and \$4ROM) and (firmware near2 (patch OR upgrad\$3))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/14 10:53
	2	(((boot adj image) and network) and firmware) and \$4ROM) and ((flash OR bios) near2 (patch OR upgrad\$3))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/14 10:54
	203	((boot adj image) and network) and \$4ROM	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/14 10:56
	115	network same transfer\$4 same boot\$4 same image	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/14 11:08

-	73	(network same transfer\$4 same boot\$4 same image) and install\$5	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/14 11:08
-	30	((network same transfer\$4 same boot\$4 same image) and install\$5) and firmware	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/14 11:08
-	3	("5452454" "5623604" "5870610").PN.	USPAT	2004/10/14 11:17
-	9	("5303380" "5325532" "5933631" "5933652" "5948101" "6009497" "6370645" "6381693" "6401201").PN.	USPAT	2004/10/14 11:31
-	0	6745324.URPN.	USPAT	2004/10/14 11:39
-	7	6266809.URPN.	USPAT	2004/10/14 11:42
-	4	bootable near2 kernel	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 11:47
-	89	bootable near2 image	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 11:47
-	1578	717/168-178.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 11:47
-	6	(bootable near2 image) and 717/168-178.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 11:55
-	1	((bootable near2 image) and 717/168-178.ccls.) and firmware with (install\$5 OR upgrad\$3 OR updat\$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 11:56
-	14	(bootable near2 image) and firmware with (install\$5 OR upgrad\$3 OR updat\$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 12:00
-	10	("5269022" "5469573" "5727213" "5812748" "5907672" "5930824" "6029232" "6088815" "6134673" "6154852").PN.	USPAT	2004/10/25 11:58
-	943	almeida.in.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 12:00

	1	almeida.in. and boot	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 12:00
	4661	719.clas.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 12:00
	117	719.clas. and boot and firmware	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 12:01
	129	719.clas. and boot\$4 and firmware	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 12:01
	10	(719.clas. and boot\$4 and firmware) and ((updat\$3 OR upgrad\$3 OR install\$5) near2 firmware)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 12:03
	13	(719.clas. and boot\$4 and firmware) and ((updat\$3 OR upgrad\$3 OR install\$5) near3 firmware)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 12:04
	2631	((updat\$3 OR upgrad\$3 OR install\$5) near3 firmware)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 12:04
	936	((updat\$3 OR upgrad\$3 OR install\$5) near3 firmware)) and \$2boot\$4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 12:05
	66	(((updat\$3 OR upgrad\$3 OR install\$5) near3 firmware)) and \$2boot\$4) and 717/168-178.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 12:05
	20	(US-6745324-\$ or US-6266809-\$ or US-5948101-\$ or US-5210854-\$ or US-6539473-\$ or US-6275931-\$ or US-5901225-\$ or US-6324692-\$ or US-6615404-\$ or US-6594757-\$ or US-5325532-\$ or US-5878256-\$ or US-6167567-\$ or US-5826015-\$ or US-5859911-\$ or US-6009500-\$ or US-6438688-\$ or US-6581157-\$ or US-5623604-\$ or US-5452454-\$).did.	USPAT	2004/10/25 12:51

	1	((US-6745324-\$ or US-6266809-\$ or US-5948101-\$ or US-5210854-\$ or US-6539473-\$ or US-6275931-\$ or US-5901225-\$ or US-6324692-\$ or US-6615404-\$ or US-6594757-\$ or US-5325532-\$ or US-5878256-\$ or US-6167567-\$ or US-5826015-\$ or US-5859911-\$ or US-6009500-\$ or US-6438688-\$ or US-6581157-\$ or US-5623604-\$ or US-5452454-\$).did.) and installer	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 12:46
	66	boot\$4 with firmware with (patch OR upgrade OR application OR file)	USPAT	2004/10/25 13:10
	1	(firmware with (patch OR upgrade OR application OR file)) same (boot near2 logic)	USPAT	2004/10/25 13:11
	1	(firmware with (patch OR upgrade OR application OR file)) same (boot\$1logic)	USPAT	2004/10/25 13:11
	14	("5268928" "5414751" "5418524" "5781921" "5787288" "5812857" "5822692" "5878256" "5937198" "6055632" "6073207" "6141795" "6253281" "6275931").PN.	USPAT	2004/10/25 13:23
	21	(US-6438688-\$ or US-5325532-\$ or US-6615404-\$ or US-6266809-\$ or US-6539473-\$ or US-6745324-\$ or US-6581157-\$ or US-6594757-\$ or US-6324692-\$ or US-6275931-\$ or US-5859911-\$ or US-5901225-\$ or US-6009500-\$ or US-5210854-\$ or US-5826015-\$ or US-5623604-\$ or US-5452454-\$ or US-6167567-\$ or US-6640334-\$ or US-5878256-\$ or US-5948101-\$).did.	USPAT	2004/10/25 15:15
	9	((US-6438688-\$ or US-5325532-\$ or US-6615404-\$ or US-6266809-\$ or US-6539473-\$ or US-6745324-\$ or US-6581157-\$ or US-6594757-\$ or US-6324692-\$ or US-6275931-\$ or US-5859911-\$ or US-5901225-\$ or US-6009500-\$ or US-5210854-\$ or US-5826015-\$ or US-5623604-\$ or US-5452454-\$ or US-6167567-\$ or US-6640334-\$ or US-5878256-\$ or US-5948101-\$).did.) and install (flash OR firmware) with (bootable)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 15:19
	81	((flash OR firmware) with (bootable)) and install\$5 and network	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 15:19
	29	((flash OR firmware) with (bootable)) and install\$5 and network	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 15:43

	3731	marsh.in.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 15:27
	35	marsh.in. and firmware	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 15:28
	147	(firmware with update\$3).ti.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 15:47
	21	((firmware with update\$3).ti.) and boot\$4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 16:11
	1578	717/168-178.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 16:11
	179	717/168-178.ccls. and (boot\$4 with (OS OR (operating adj system)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 16:16
	86	(717/168-178.ccls. and (boot\$4 with (OS OR (operating adj system)))) and (firmware OR bios)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 16:32
	154	(patch OR upgrade) with requir\$3 with (firmware OR bios OR flash)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 17:20
	18	((patch OR upgrade) with requir\$3 with (firmware OR bios OR flash)) and 717/168-178.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 17:20
	27	("5388267" "5452339" "5473775" "5522076" "5535355" "5568641" "5579522" "5592669" "5630093" "5647986" "5666293" "5701492" "5748940" "5812883" "5930358" "5940074" "5966301" "6029046" "6035423" "6055632" "6085299" "6135651" "6148441" "6185678" "6253281" "6308265" "6385721" "2001/0026472").PN.	USPAT	2004/10/25 16:50

	27	("5388267" "5452339" "5473775" "5522076" "5535355" "5568641" "5579522" "5592669" "5630093" "5647986" "5666293" "5701492" "5748940" "5812883" "5930358" "5940074" "5966301" "6029046" "6035423" "6055632" "6085299" "6135651" "6148441" "6185678" "6253281" "6308265" "6385721" "2001/0026472").PN.	USPAT	2004/10/25 17:18
	746	(OS OR (operating adj system)) with requir\$3 with (firmware OR bios OR flash)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 17:21
	117	(OS OR (operating adj system)) with requir\$3 with (firmware OR bios OR flash) with (patch OR upgrad\$3 OR updat\$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 17:21
	6	((OS OR (operating adj system)) with requir\$3 with (firmware OR bios OR flash) with (patch OR upgrad\$3 OR updat\$3)) and 717/168-178.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 17:24
	11	((OS OR (operating adj system)) with requir\$3 with (firmware OR bios OR flash)) and 717/168-178.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 17:39
	15	717/168-178.ccls. and (boot adj (code OR loader)) with (firmware OR bios)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 17:40
	3080	(firmware OR BIOS) near2 (upgrad\$3 OR updat\$3 OR install\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 18:20
	232	(firmware OR BIOS) with (boot adj code)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 18:20
	11	717/168-178.ccls. and ((firmware OR BIOS) with (boot adj code))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 18:53
	10	5854937.URPN.	USPAT	2004/10/25 18:21
	9	("5101490" "5579522" "5727170" "5835933" "5854937" "5873112" "6195511" "6292868" "6327652" "2002/0016908").PN.	USPAT	2004/10/25 18:31
	65	5579522.URPN.	USPAT	2004/10/25 18:33

	25	("4928237" "5022077" "5063496" "5072370" "5128995" "5136713" "5187792" "5230052" "5257380" "5327531" "5355489" "5388267" "5410699" "5410707" "5418918" "5465357" "5471674" "5473775" "5481713" "5488741" "5495611" "5497490" "5579522" "5692190" "5694600").PN.	USPAT	2004/10/25 18:47
	76	(operating adj system) with replac\$3 with (firmware OR bios)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 18:55
	688	(operating adj system) near2 (firmware)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/25 18:55
	1129	713/2.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/26 10:38
	188	713/2.ccls. and firmware and (operating adj system) and network	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/26 10:33
	111	713/2.ccls. and (firmware same (operating adj system)) and network	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/26 10:34
	69	713/2.ccls. and (firmware with (operating adj system)) and network	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/26 10:34
	91	((firmware OR BIOS) with (upgrad\$3 OR updat\$3 OR install\$5 OR replac\$3)) and (boot\$4 adj (image OR kernel OR memory))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/26 11:45
	28	713/2.ccls. and (((firmware OR BIOS) with (upgrad\$3 OR updat\$3 OR install\$5 OR replac\$3)) and (boot\$4 adj (image OR kernel OR memory)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/26 10:39
	9	("5101490" "5579522" "5727170" "5835933" "5854937" "5873112" "6195511" "6292868" "6327652" "2002/0016908").PN.	USPAT	2004/10/26 11:43
	521	((firmware OR BIOS) with (upgrad\$3 OR updat\$3 OR install\$5 OR replac\$3)) with (operating adj system)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/26 11:45

	41	((firmware OR BIOS) with (upgrad\$3 OR updat\$3 OR install\$5 OR replac\$3)) with (operating adj system)) and 717/168-178.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/26 11:51
	437	717/171-173.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/26 11:51
	32	717/171-173.ccls. and firmware and boot\$4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/26 11:55
	333	(operating adj system) with requir\$3 with (firmware OR bios)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/26 11:56
	38	((operating adj system) with requir\$3 with (firmware OR bios)) and (713/2.ccls. OR 717/171-173.ccls.)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/26 11:56